

Lead in Water Remediation Plan

Pursuant to the requirement of *Subpart 67-4: Lead Testing in School Drinking Water* the Kingston City School District tested all water outlets that could be used for drinking or cooking purposes. Some of these outlets tested above the 15 ppb action level. These outlets were taken out of service as soon as laboratory reports were received and reviewed by the district. Our remediation efforts are described below.

Remediation Key

| | |
|---|--|
| A | Replaced plumbing components |
| B | Replaced plumbing fixture |
| C | Replaced plumbing fixture & accessible piping |
| D | Took fixture permanently of service |
| E | Took fixture out service and posted pending permanent solution |
| F | Posted as non-potable |

| Building Location # | Location | Sample Result | Remediation | Post Sample Result |
|---------------------|-------------------|---------------|-------------|--------------------|
| Crosby 2 | Principal sink | 39 | F | |
| Crosby 6 | Girls rm sink | 79 | F | |
| Crosby 8 | Rm 12 sink | 23 | F | |
| Crosby 10 | Slop Sink | 24 | F | |
| Crosby 17 | Girls LM | 27 | F | |
| Crosby 18 | Coach office sink | 29 | F | |
| Crosby 27 | Portable #1 | 27 | F | |

| | | | | |
|-----------|---------------------|----|---|--|
| | sink | | | |
| Crosby 29 | Portable #2 sink | 27 | F | |
| Crosby 30 | Portable #2 sink | 22 | F | |
| Crosby 31 | Portable #2 sink | 21 | F | |
| Crosby 34 | Portable #3 sink | 29 | F | |
| Crosby 35 | Portable #3 sink | 22 | F | |
| Crosby 41 | Teacher's rm | 17 | F | |
| Crosby 43 | Library sink | 19 | F | |
| Crosby 44 | Rm 13 sink | 20 | F | |
| Crosby 49 | Rm 22 Sink | 17 | F | |
| Crosby 51 | Rm 20 Sink | 18 | F | |

| | | | | |
|-----------|----------------------|-----|---|--|
| Graves 2 | Lt Kitchen faucet | 64 | F | |
| Graves 23 | Girls rm sink | 25 | F | |
| Graves 25 | Berardi sink | 34 | F | |
| Graves 29 | Rm 12 sink | 22 | F | |
| Graves 38 | Rm 10 fountain | 140 | D | |
| Graves 41 | Rm 6 sink | 21 | F | |
| Graves 42 | Rm 6 fountain | 73 | D | |
| Graves 43 | Rm 1 sink | 35 | F | |
| Graves 49 | Rm 3 sink | 51 | F | |
| Graves 55 | Rm 5 fountain | 27 | D | |
| Graves 56 | Rm 7 sink | 28 | F | |

| | | | | |
|-----------|----------------|----|---|--|
| Graves 57 | Rm 7 fountain | 93 | D | |
| Graves 60 | Rm11 sink | 33 | F | |
| Graves 62 | Rm 13 sink | 57 | F | |
| Graves 63 | Rm 13 fountain | 30 | D | |
| Graves 68 | Portable sink | 17 | F | |

| | | | | |
|-------|----------------|-----|---|--|
| GW 6 | Slop sink | 56 | F | |
| GW12 | Rm 103 sink | 17 | F | |
| GW 14 | Rm 105 sink | 20 | F | |
| GW 15 | Rm 105 sink | 17 | F | |
| GW 35 | Rm214 sink | 20 | F | |
| GW 45 | Rm 205 sink | 22 | F | |
| GW 53 | Girls sink | 48 | F | |
| GW 63 | Fountain rm 14 | 440 | D | |

| | | | | |
|--------|----------------------------------|----|---|--|
| JFK 16 | Rm 123 fountain | 18 | F | |
| JFK 17 | Coach's office sink | 59 | F | |
| JFK 18 | Coach's office sink | 88 | F | |
| JFK 47 | Rm 207 fountain | 18 | D | |
| JFK 58 | Rm 206 sink | 17 | F | |
| JFK 63 | Boy's 2 nd floor sink | 46 | F | |

| | | | | |
|--------|------------------|----|---|--|
| Myer 1 | Art room | 28 | F | |
| Myer 2 | Room 3A fountain | 28 | E | |
| Myer 3 | 3A sink | 36 | F | |
| Myer 5 | Room 3B sink | 80 | F | |
| Myer 6 | Gang boy's | 85 | F | |

| | | | | |
|---------|----------------------------|-----|---|--|
| | sink | | | |
| Myer 7 | Gang girls sink | 73 | F | |
| Myer 9 | Room 5 fountain | 30 | E | |
| Myer 10 | Kitchen hand wash sink | 20 | F | |
| Myer 11 | Kitchen sprayer dishwasher | 46 | F | |
| Myer 12 | Kitchen Food Prep | 81 | E | |
| Myer 13 | Kitchen TR sink | 39 | F | |
| Myer 14 | Staff bath at rm 7 sink | 32 | F | |
| Myer 15 | Nurse rm sink | 81 | F | |
| Myer 16 | Nurse rm Stainless | 25 | F | |
| Myer 18 | Library sink | 72 | F | |
| Myer 20 | Room 19 sink | 18 | F | |
| Myer 21 | Room 21 sink | 21 | F | |
| Myer 23 | Room 23 Fountain | 26 | E | |
| Myer 24 | Room 25 sink | 17 | F | |
| Myer 25 | Room 24 sink | 22 | F | |
| Myer 27 | Room 16 sink | 25 | F | |
| Myer 37 | Room 32 sink | 18 | F | |
| Myer 38 | Room 31 sink | 19 | F | |
| Myer 39 | Room boiler rm slop sink | 110 | F | |
| Myer 41 | Water fountain Café | 16 | F | |
| Myer 44 | Boiler sink | 16 | F | |

| | | | | |
|----------|-----------------|-----|---|--|
| Edson 12 | Staff bath sink | 610 | F | |
| Edson 13 | Custodial sink | 20 | F | |
| Edson 23 | Rm 40-B sink | 28 | F | |

| | | | | |
|-----------|---------------|-----|---|--|
| Edson 26 | B26 slop sink | 18 | F | |
| Edson 29 | B-19 sink | 16 | F | |
| Edson 103 | C-12 sink | 28 | F | |
| Edson 117 | C-16 sink | 22 | F | |
| Edson 203 | A-5 Art sink | 890 | F | |

| | | | | |
|-------|----------------------|-----|---|--|
| | Principal bath sink | 18 | F | |
| | Staff bath J114 | 26 | F | |
| | Room 113 sink 1 | 19 | F | |
| | Room 113 sink 2 | 35 | F | |
| | Room 113 sink 3 | 320 | F | |
| | Room 113 Sink 4 | 23 | F | |
| | Room 115 sink 1 | 23 | F | |
| | Room 115 Sink 2 | 140 | F | |
| | Room 115 sink 3 | 91 | F | |
| | Room 115 sink 4 | 20 | F | |
| | Staff Men's sink 1 | 38 | F | |
| | Staff Men's sink 2 | 17 | F | |
| | Staff Men's sink 3 | 20 | F | |
| | Staff women's sink 1 | 19 | F | |
| | Staff women's sink 2 | 19 | F | |
| | Room 119T | 24 | F | |
| JWB 2 | Main office sink | 22 | F | |

| | | | | |
|---------|---------------------------------------|-----|---|--|
| JWB 6 | Rm 7 sink | 18 | F | |
| JWB 22 | Library sink | 22 | F | |
| JWB 34 | Rm 13 sink | 39 | F | |
| JWB 36 | Teacher room | 32 | F | |
| JWB 38 | Copy room | 890 | F | |
| JWB 79 | Rm 200 sink | 16 | F | |
| JWB 83 | Rm 202 | 31 | F | |
| JWB 90 | Rm 203 sink #4 | 31 | F | |
| JWB 106 | Central kitchen men's room sink | 17 | F | |
| JWB121 | 301 men's rm sink | 17 | F | |
| JWB209 | Slop sink by ramp | 64 | F | |
| JWB 211 | Slop sink sprinkler rm | 17 | F | |

| | | | | |
|-------------|-----------------------------------|----|---|--|
| KHS Main 01 | Boiler rm sink | 16 | F | |
| KHS Main 06 | Music wing boy's rm RH sink | 24 | F | |
| KHS Main 14 | Nurse area toilet rm sink | 17 | F | |
| KHS Main 20 | Rm 10 sink | 37 | F | |
| KHS Main 31 | Stage sink | 92 | F | |
| KHS Main 33 | Principal's sink | 22 | F | |

| | | | | |
|--------------------|---------------------|----|---|--|
| Field House 415 | Boiler room sink | 32 | F | |
|--------------------|---------------------|----|---|--|

| | | | | |
|---------|------------|----|---|--|
| MJM 705 | Men's sink | 16 | F | |
|---------|------------|----|---|--|

Carnegie and Chambers had no sites needing remediation.